

**Building Services**  
**November 2020 Building Permit Activity Report**  
**Date Range 11/1/2020 - 11/30/2020**

Construction Type	Units	Permits	Value	Reported Sq Ft
101 Single Family	57	57	15,056,354	57
102 Single Family	1	1	320,000	1
103 Two-Family	1	1	275,000	1
104 Three/Four Family	0	0	0	0
105 Multi Family	304	12	15,911,605	12
106 Manufactured Home	0	0	0	0
<b>Total 101-106</b>	<b>363</b>	<b>71</b>	<b>\$31,562,959.00</b>	<b>71</b>
213 Hotel/Motel	0	0	0	0
214 Other Shelter	0	0	0	0
<b>Total 213-214</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>	<b>0</b>
318 Amusement/Social/Recreational	1	1	623,124	4,463
319 Churches	0	0	0	0
320 Industrial	0	0	0	0
321 Parking Garages	10	10	28,004,461	461,031
322 Service Repair Garages	0	0	0	0
323 Hospitals/Institutions	0	0	0	0
324 Office/Banks/Professional Bldgs.	0	0	0	0
325 Public Works/Utilities	0	0	0	0
326 Schools/Educational Facilities	0	0	0	0
327 Stores/Customer Service	1	1	1,600,000	20,442
328 Other Nonresidential Buildings	1	1	16,250	650
329 Structures Other Than Buildings	0	0	0	0
<b>Total 318-329</b>	<b>13</b>	<b>13</b>	<b>\$30,243,835.00</b>	<b>486,586</b>
434 Residential Additions/Alterations	872	841	14,773,059	1,569,937
437 Commercial Additions/Alterations	121	121	41,957,381	737,660
438 Residential Garages	2	2	51,836	1,892
<b>Total 434-438</b>	<b>995</b>	<b>964</b>	<b>\$56,782,275.15</b>	<b>2,309,489</b>
645 1 Family Demolition	10	10	98,344	16,921
646 2 Family Demolition	0	0	0	0
647 3-4 Family Demolition	0	0	0	0
648 5 or More Family Demolition	0	0	0	0
649 All Other Demolition	10	10	53,700	14,855
<b>Total 645-649</b>	<b>20</b>	<b>20</b>	<b>\$152,044.00</b>	<b>31,776</b>
<b>TOTAL DEMOLITION**</b>	<b>20</b>	<b>20</b>	<b>\$152,044.00</b>	<b>31,776</b>
<b>TOTAL RESIDENTIAL</b>	<b>1,237</b>	<b>914</b>	<b>\$46,387,853.58</b>	<b>1,571,900</b>
<b>TOTAL COMMERCIAL</b>	<b>134</b>	<b>134</b>	<b>\$72,201,215.57</b>	<b>1,224,246</b>
<b>GRAND TOTAL*</b>	<b>1,391</b>	<b>1,068</b>	<b>\$118,741,113.15</b>	<b>2,827,922</b>

\*(Does not include demolitions in the final count)

\*\* (Demo values and sqft has not been reported consistently by customers)